

REVISION LETTER	GE ALTERATION NOTICE NUMBER

**INSTRUCTION MANUAL IM-220**

**Cleaning Procedure of the  
Conical Threads on Riverhawk Studs**

<b>GE Power Generation</b>		GENERAL ELECTRIC COMPANY Schenectady, NY	
<b><u>VENDOR SUPPLIED DRAWING</u></b>			
GE NOT TO REVISE. GE REVISION LEVEL IS AS SHOWN ON THIS APPLIQUE. THIS DOCUMENT IS FILED UNDER THE GE DRAWING NUMBER			
THIS DOCUMENT SHALL BE REVISED IN ITS ENTIRETY. ALL SHEETS OF THIS DOCUMENT ARE THE SAME REVISION LEVEL AS INDICATED IN THIS VENDOR SUPPLIED DRAWING APPLIQUE			
FIRST MADE FOR:		___ OF ___	
GE SIGNATURES	DATE	GE DRAWING NUMBER	REV
CHECKED		<b>373A4025</b>	-
ISSUED			

The Riverhawk Company reserves the right to make changes updating this document without dissemination or notice. The latest revision level may be obtained by contacting Riverhawk Company directly or visit our website at [www.riverhawk.com](http://www.riverhawk.com)



215 Clinton Road.  
New Hartford, NY 13413  
Tel: 315-768-4855  
Fax: 315-768-4941  
Email: [info@riverhawk.com](mailto:info@riverhawk.com)

Instruction Manual IM-220  
Cleaning Procedure of the  
Conical Threads on Riverhawk Studs

Table of Contents

Section	Description	Page Number
1.0	Cautions and Safety Warnings	3
2.0	Scope and GE Part Number Cross-Reference	3
3.0	Required Equipment	3
4.0	Cleaning Procedure	4
5.0	Storage Instructions	7
6.0	Revision History	8



215 Clinton Road.  
New Hartford, NY 13413  
Tel: 315-768-4855  
Fax: 315-768-4941  
Email: info@riverhawk.com

GE DRAWING NUMBER	REV.
373A4025	-
FIRST MADE FOR:	SH.

Instruction Manual IM-220  
Cleaning Procedure of the  
Conical Threads on Riverhawk Studs

## 1.0 Cautions and Safety Warnings

### CAUTION

Personal injury and equipment damage can occur if the proper health and safety codes and procedures are not followed. Contact the site's health and safety office to determine all applicable safety rules and regulations.

### WARNING

The proper personal safety equipment must be worn at all times.

## 2.0 Scope

This document describes the steps necessary to clean the internal, conical thread of a Riverhawk-supplied engineered stud.

GE Purchasing Ordering Part Number	GE Drawing Number	Riverhawk Part Number	Description
	373A4026	GT-4253	Stud Cleaning Kit
	373A4027	GT-4354	Stud Cleaning Kit

## 3.0 Required Equipment

### 3.1 Hand Tools

Compressed air hose with an air blowgun attachment  
Variable-speed, electric hand-drill

### 3.2 Special Tools

Stud Cleaning Kit: GT-4253 for 2" [51mm] Studs and larger sizes  
GT-4354 for 1.625" [42mm] Studs or smaller



215 Clinton Road.  
New Hartford, NY 13413  
Tel: 315-768-4855  
Fax: 315-768-4941  
Email: info@riverhawk.com

GE DRAWING NUMBER	REV.
373A4025	-
FIRST MADE FOR:	SH.

Instruction Manual IM-220  
Cleaning Procedure of the  
Conical Threads on Riverhawk Studs

4.0 Cleaning Procedure

4.1 Cleaning Riverhawk Locknuts



Sample Picture of a Riverhawk Locknut

For new installations, the nuts should come sealed from the factory and will need no cleaning.

For existing installations, please refer to the Riverhawk installation manual for your specific hardware set.



215 Clinton Road.  
New Hartford, NY 13413  
Tel: 315-768-4855  
Fax: 315-768-4941  
Email: info@riverhawk.com

GE DRAWING NUMBER	REV.
373A4025	-
FIRST MADE FOR:	SH.

Instruction Manual IM-220  
Cleaning Procedure of the  
Conical Threads on Riverhawk Studs

#### 4.2 Cleaning Riverhawk Studs

For new installations, the studs should come sealed from the factory and will need no cleaning.

For previously installed studs, a clean conical thread should have a bright and shiny appearance. It must be free from any loose or hardened dirt and/or debris.

If cleaning is required, follow these steps:

1. Blow out the threads with compressed air to remove loose debris and dry conical threads. Do not apply a solvent or other cleaning solution to the threads as this may chemically attack the stud.



**Picture of an air hose with an Air Blowgun attachment**

2. Use Stud Cleaning Kit, GT-4354 or a similar 1/2" [12mm] diameter Brass power brush for Riverhawk studs that are 1.625" [42mm] or smaller in diameter.

Use Stud Cleaning Kit, GT-4253 or a similar 1" [25mm] diameter Brass power brush for Riverhawk studs that are 2" [51mm] or larger in diameter.



**Picture of Brass Power Brush**



215 Clinton Road.  
New Hartford, NY 13413  
Tel: 315-768-4855  
Fax: 315-768-4941  
Email: info@riverhawk.com

GE DRAWING NUMBER	REV.
373A4025	-
FIRST MADE FOR:	SH.

Instruction Manual IM-220  
Cleaning Procedure of the  
Conical Threads on Riverhawk Studs

Do not use a worn brush. A worn brush can not reach and clean the bottom of the thread root. It can also lead to unintentional damage to the conical thread.



Picture of a slightly worn brush  
Replace Soon



Picture of a worn brush  
Replace now. Do not use.

3. Insert the brush into an electric drill and set drill to run in a counterclockwise direction at high speed.



Picture of a brush mounted on a drill



215 Clinton Road.  
New Hartford, NY 13413  
Tel: 315-768-4855  
Fax: 315-768-4941  
Email: info@riverhawk.com

GE DRAWING NUMBER	REV.
373A4025	-
FIRST MADE FOR:	SH.

**Instruction Manual IM-220  
Cleaning Procedure of the  
Conical Threads on Riverhawk Studs**

4. Work the drill in a circular motion while moving the brush in and out to clean all of the threads. Try not to hold the brush in one place too long, so as not to remove the stud's protective coating.



**Pictures of brush cleaning of a stud**

5. Blow out the threads with compressed air to remove loosened debris.
6. Visually inspect threads for cleanliness. Threads should be bright and shiny.
7. Repeat if any dirt can be seen in the threads.
8. Inspect threads for any damage (i.e. - missing, torn, ripped threads) that may have been caused by previous installation.

### **5.0 Storage Instructions**

Clean the brush with a solvent to remove any dirt or debris. Rinse the brush with acetone and allow to air dry.

Store brushes and instructions in a suitable container and location that will protect them from moisture and dirt.



215 Clinton Road.  
New Hartford, NY 13413  
Tel: 315-768-4855  
Fax: 315-768-4941  
Email: info@riverhawk.com

GE DRAWING NUMBER	REV.
373A4025	-
FIRST MADE FOR:	SH.

Instruction Manual IM-220  
Cleaning Procedure of the  
Conical Threads on Riverhawk Studs

6.0 Revision History

Revision Letter	Effective Date	Description
-	Jan 16, 2009	Released



215 Clinton Road.  
New Hartford, NY 13413  
Tel: 315-768-4855  
Fax: 315-768-4941  
Email: info@riverhawk.com

GE DRAWING NUMBER	REV.
373A4025	-
FIRST MADE FOR:	SH.